

通用汽车记分卡截屏图像

背景

对于所有 IATF 16949 审核，根据“获得并保持 IATF 认可的规则第六版”，有三个关键步骤可确保制定稳健的考虑了绩效的审核计划：

规则 5.7.1 h) “外部绩效目标完成情况和相关趋势，包括自先前审核以来的顾客报告和记分卡、顾客满意度和顾客投诉总结；”

规则 5.7.2 审核计划“审核组成员应对客户提供的审核策划信息进行分析”

规则 5.7.2 b) “与最高管理者一起召开的首次会议涵盖……包括评审当前顾客的报告和/或积分卡……”

通用汽车记分卡 IATF 16949 快速参考指南明确了上述各项规则所述步骤相关的记分卡、信息和要求，作为 IATF 16949 审核的一部分。

本文件提供了相关的参考记分卡和其他绩效指标的截屏图像，可视化展示了通用汽车记分卡 IATF 16949 快速参考指南中确定的客户绩效评估指标。

通用汽车记分卡 IATF 16949 快速参考指南可访问 [IATF Globaloversight](#) 网页获取。

目录表，显示所提供的 **GM Supply Power** 截屏图像示例

屏幕图像/表格名称	页码
SCMS 供应商记录界面	2
详细影响报告	3
CS 2 通知函示例	4
可采购性报告	5
详细影响报告	5
载明整车/动力系统发运暂停详细影响报告	6
载明市场措施的详细影响报告	6
如何查阅可采购性报告和详细影响报告	7
详细影响报告结构	7
NBH 和市场措施详情	7
如何查阅 SPPS 记录信息	8
完整的 SPPS 详细报告示例	10

通用汽车记分卡截屏图像

SCMS 供应商记录界面 显示有客户名称、制造邓白氏编码、城市和州，箭头标记如下。

对邓白氏（DUNS）编号的说明如下：

- Cottage DUNS（前 3 位是零“000”）通常为支持场所或二级签约的分供方场所
- Ultimate DUNS 编号表示该公司的母公司或集团公司，不是制造场所
- Shipping DUNS，签约的物流仓库，从该仓库发运成品给 GM，不是制造场所
- Header DUNS，通常为用于投标和合约签署的销售办公室，不是制造场所
- 制造 DUNS 编号是产品制造现场的编号，对零件质量/物流负责
- 本示例为通用汽车的一个现场的例子

通用汽车当前质量绩效要求（QPR）的详细信息，可在 [GM SupplyPower](#) 下的 Document Library 中查阅，包括：GM 1927 17、通用汽车质量绩效要求（QPR）和 SQEA 要求、CG 4338 GM 1927 03 供应商质量 SOR（要求声明）等。更改内容见 [SupplyPower](#)。

通用汽车记分卡截屏图像

详细影响报告，载明了严重度、生产中断和 SPPS 描述。同时报告中也载明了其他详细信息。

gm		Impact Detail Report																																
		Mfg DUNS: 123456789 - Anywhere USA Ult DUNS: 987654321																																
		Mfg DUNS Location: 123 MAIN ST																																
		KEOKUK, IA - 526322259 - US - GMNA																																
<table border="1"> <thead> <tr> <th colspan="2">Effective Date</th><th colspan="7">Expiration Date</th></tr> </thead> <tbody> <tr> <td colspan="2">IATF 16949: CERT</td><td colspan="7" rowspan="2">08/19/2021 08/18/2024</td></tr> <tr> <td colspan="9"> PSA: SQEA: 2016, 2017 NBH: N/A </td></tr> </tbody> </table>								Effective Date		Expiration Date							IATF 16949: CERT		08/19/2021 08/18/2024							PSA: SQEA: 2016, 2017 NBH: N/A								
Effective Date		Expiration Date																																
IATF 16949: CERT		08/19/2021 08/18/2024																																
PSA: SQEA: 2016, 2017 NBH: N/A																																		
Issue Date	SPPS/SCMS#	Status	Direct Impact	Severity Score/Impact	Type	Master Process Name	Primary N/C	Secondary N/C																										
06/11/2022	[REDACTED]	Closed	Quality - CCA	5	CCA - Shipment Quality		Packaging	Parts not packaged to specification for service																										
07/11/2022	[REDACTED]	Closed	GSC Rating - CCA	5	CCA - Supply Chain		Shipping	Documentation / Paperwork Discrepancies																										
02/11/2022	[REDACTED]	Closed	Sourceability Level	0.25	Quality																													
06/11/2022	[REDACTED]	Closed	Sourceability Level	1	Quality																													
11/16/2022	[REDACTED]	Analyzing	Sourceability Level	0.5	Quality																													

注:

详细影响报告中“直接影响”项下列出的全部问题，不论其类型（可采购性级别、CCA、GSC-物流等），都需要制定纠正措施计划，并影响客户评级。

SPPS/SCMS#一列含 SPPS 记录编号。请注意，SCMS 供应商记录（而非 SPPS 记录）中提供了 NBH/服务中断/市场措施的详细信息。

状态栏明确了 SPPS 问题的状态，各状态的定义参见 **GM 1927-17 SQ 过程和评估程序**。

GM 1927-17 SQ 过程和评估程序中以矩阵形式对严重度评级作了说明。

它是过去 6 个月内所有问题的严重度评分的总和。在客户可采购性等级是 5 级时，要参考过去 12 个月的质量历史数据。此外，认证机构审核员应采用严重度评分确定待评审的问题的优先级。

通用汽车记分卡截屏图像

CS 2 通知函示例

Subject: General Motors SPPS 000 – Entry into Controlled Shipping Level 2

TO LIST: test@test.com; test@gm.com

CC LIST: test2@gm.com

Date: 31-May-2019 3:28 PM ET

Supplier Name

Title

000000000 – Supplier Name

Street Address

City, State, Country Zip code

Controlled Shipping is part of General Motors Supplier Quality Processes and Measurements Procedure and is part of the Supplier Quality Improvement Process. General Motors has determined that current controls by your organization are not sufficient to insulate GMPT-WARREN TRANSMISSION from the receipt of nonconforming parts/material produced by your facility. This letter is formal notification and confirms discussions held with Supplier Name that your facility has been placed in Controlled Shipping Level 2 for the following nonconformances:

Part Number	Part Name	SPPS #	Nonconformance
00000000	Part Name	000	Nonconformance description

Links to SPPS Application:

[GM/JV Users click here](#)

[Supplier Users click here](#)

The procedures you have enacted to date have been insufficient in stopping the flow of nonconforming material to our plants. Therefore, **you must immediately:**

- Implement and pay the costs of a GM-defined containment activity over and above your current process controls and containment activity.** The GM-defined containment activity is in addition to the current controls and containment activity.
- Clearly identify the qualified shipments. Clearly document and communicate post Corrective Action Break-Points to the Controlled Shipping Provider.**
- Identify the root cause of the nonconformance(s).**
- Define and implement irreversible corrective action for the root cause(s) of the problem(s).** This will normally include revised FMEAs, process flow diagrams, and process control plans.
- Validate effectiveness of the corrective action.** Outline your plan for reviewing your controlled shipping data.
- Track and report your progress by using a GM-approved report format. You must submit regular reports as specified by the GM representative monitoring this activity.**
- Meet the defined exit criteria.** The parts will remain in controlled shipping until irreversible corrective actions are implemented and confirmed. Exit criteria will be established that verify the identification of the true root cause, and verify that appropriate corrective action is implemented, properly documented, and effective.
- Notify your IATF 16949 registrar of the CS2 status.** You are to notify your certification registrar, in writing, within five (5) working days when a customer places you in Controlled Shipping Level 2.

Note: Failure to comply with this process, or the inability to implement a successful action plan or containment activity, will result in the implementation of new business hold. Reference the GM Supplier Quality Processes and Measurements Procedure at GM SupplyPower for additional details concerning Controlled Shipping.

If you have any questions, contact GM Person Name, Title phone, [email](#), who will be monitoring and defining your controlled shipping activities.

Sincerely,


GM Person Name

Title

Department

通用汽车记分卡截屏图像

可采购性报告



注:

图例上显示了每个指标的可能评级和颜色

项目启动绩效是对 APQP 合规性的评级

NBH=新业务暂停 (NBH) (此处 N/A 表示客户未处于 NBH 状态)

通用汽车的 IATF 认证状态等级包括已认证、豁免、暂停以及因各种原因而未认证

GSC 表示交付绩效 (售后服务件和正常生产件, 两个进行单独评级)

CCA (客户服务和售后服务) 表示服务情况 - 显示质量和交付评级

可采购性报告中的任何红色评级, 请转到详细影响报告, 确定相关问题

可采购性报告中的其他评级未用于审核 (场所和财务风险、冲突材料、多样性)

通用汽车的新供应商有一份可采购性报告, 但相应的评级 (可采购性级别可能为 1 级或 0 级) 可能不适用

单击可采购性报告中的制造商 DUNS 编号, 转至详细影响报告。

载明严重度评分和问题类型的详细影响报告。

Impact Detail Report
Mfg DUNS Location: 123456789 - TESTING - CITY, STATE, REGION

Severity Score/Impact	Type	Primary N/C	Secondary N/C	Major Disruption	Customer Impact
5	CCA - Shipping/Quality	Packaging	Parts not packaged to specification for service		
2	CCA - Supply Chain	Shipping	Electronic Communication Discrepancies		
0.5	Quality			Single Occurrence	Part installed in Vehicle/Eng or Tra
0.5	Quality			Single Occurrence	Part installed in Vehicle/Eng or Tra
2	Quality			Repeat Occurrence	Part installed in Vehicle/Eng or Tra
0.5	Quality			Single Occurrence	Part installed in Vehicle/Eng or Tra
0.5	Quality			Repeat Occurrence	Incoming part. Not installed in Sub-
2	Quality			Repeat Occurrence	Part installed in Vehicle/Eng or Tra
0.25	Quality			Single Occurrence	Part installed in Sub-assembly or \

严重度代表问题对通用汽车的影响, 详见 GM 1927 17 SQ 过程和评估程序。

通用汽车记分卡截屏图像

载明整车/动力系统发运暂停 (Yard Hold) 的详细影响报告

Impact Detail Report

Mfg DUNS Location: 123456789 - TESTING - CITY, STATE, REGION

Customer Impact	Value Stream Impact Location
Level G.2: Critical failure	Yard hold
Level F: Repeat of Level B,D or E	Parts sorting / rework (not yet assembled)
Single Occurrence	Part installed in Sub-assembly or Vehicle/Eng or Trans. Sub-assembly or Vehicle/Eng or Trans repaired before
Repeat Occurrence	Part installed in Sub-assembly or Vehicle/Eng or Trans. Sub-assembly or Vehicle/Eng or Trans repaired before
Multiple Occurrence	Part installed in Sub-assembly or Vehicle/Eng or Trans. Sub-assembly or Vehicle/Eng or Trans repaired before

载明市场措施的详细影响报告

Impact Detail Report

Mfg DUNS Location: 123456789 - TESTING - CITY, STATE, REGION

Issue Date	SPPS/SCMS#	Status	Direct Impact	Severity Score/Impact	Type	Master Process	Primary N/C	Secondary N/C	Major Disruption
06/22/2020	312894	Issued	GSC Rating - CCA	2	CCA - Supply Chain				
07/07/2022	313960	Expired	Sourceability Level	15	Field Action				Field Action
08/18/2022	318522	Expired	Sourceability Level	16	Field Action				Field Action
08/19/2022	318607	Issued	Launch Performance	1	DVPV-High Risk				
09/21/2020	321911	Closed	Sourceability Level	5	Quality				Yard hold, resulting in an increase in the customer's yard and/or the customer's shipping yard float by 40 products or more (Vehicle\Powertrain\Components) for a single issue.
11/09/2022	326849	Planning	Sourceability Level	0.5	Quality				
07/28/2022	316250	Planning	Quality - CCA	5	CCA - Part Quality	Quality	Assembly Discrepancies		

通用汽车记分卡截屏图像

如何访问可采购性报告和详细影响报告

可采购性报告

DUNS Filter

Supplier Records

Supplier: 000148528 - DIRECTED BUY TRACKING RECORD - WARREN - MI - US

Sourceability Report for DUNS Sourceability Report for Ultimate DUNS

详细影响报告

Impact Detail Report

详细影响报告的结构

Impact Detail Report

Mfg DUNS: 123456789 - Anywhere USA Mfg DUNS: 987654321

Mfg DUNS Location: 123 MAIN ST
KEOKUK, IA - 526322259 - US - GMNA

Run Date: Nov 29, 2022 7:20:21 AM

Effective Date Expiration Date													
IATF 16949: CERT	08/19/2021 08/18/2024												
PSA:													
SOEA: 2016.2017													
NBH: N/A													
Issue Date	SPPS/SCMS#	Status	Direct Impact	Severity Score/Impact	Type	Master Process Name	Primary N/C	Secondary N/C	Major Disruption	Customer Impact	Value Stream Impact Location	Potential Safety	Phase
06/11/2022	Closed	Quality - CCA	5	CCA - Shipment Quality	Packaging	Parts not packaged to specification for service						NO	
07/11/2022	Closed	GSC Rating - CCA	5	CCA - Supply Chain	Shipping	Documentation / Paperwork Discrepancies						NO	
02/11/2022	Closed	Sourceability Level	0.25	Quality					Single Occurrence	Incoming part. Not installed in Sub-assembly or Vehicle/Eng or Trans.	NO	Production	
06/11/2022	Closed	Sourceability Level	1	Quality					Multiple Occurrence	Part installed in Sub-assembly or Vehicle/Eng or Trans. Sub-assembly	NO	Production	
11/16/2022	Analyzing	Sourceability Level	0.5	Quality					Single Occurrence	Part installed in Vehicle/Eng or Trans. Vehicle/Eng or Trans entered	NO	Production	

NBH 状态以及市场措施的详情可参见 SCMS 供应商记录界面

SCMS Certification External Applications

DUNS Filter

Supplier Records

Supplier: 000148528 - DIRECTED BUY TRACKING RECORD - WARREN - MI - US

Sourceability Report for DUNS Sourceability Report for Ultimate DUNS Impact Detail Report

+ Add Record Include Expired Records Include Audit Records

Status	Record Type	Title	Effective Date	Forecast Date	Expire Date
YES	ACTION	New Business Hold	09-Aug-2019		

Surveys

Status	Survey Title	Last Modified

Attachments

Date Added	Document Name
09-Aug-2019	Directed-Buy_NBH_GM1927-71.xls

展开明细

NBH 详细信息

Directed-Buy_NBH_GM1927-71.xls

通用汽车记分卡截屏图像

如何访问 SPPS 记录详细信息

- 1) 进入 GM SPPS 系统。

Administration

Administration Tools

- Change Password
- Edit My Profile
- My Administrators

General Motors - Applications

Access	Icon	Name	Summary	Functional Area	Request	Favorite
<input checked="" type="checkbox"/>		Global Analysis Reporting Tool 2.0 - GART 2.0	► Detail	Quality		
<input checked="" type="checkbox"/>		Global Quality Tracking System Release 6 (GQTS)	► Detail	Quality		
<input checked="" type="checkbox"/>		GME Lead Connect	► Detail	Quality		
<input checked="" type="checkbox"/>		PartLink	► Detail	Quality		
<input checked="" type="checkbox"/>		Problem Resolution Tracking System (PRTS+)	► Detail	Quality		
<input checked="" type="checkbox"/>		SCMS-Viewer & Updater *Grant only ONE SCMS package per ...	► Detail	Quality		
<input checked="" type="checkbox"/>		SCMS-Viewer Only *Grant only ONE SCMS package per user *	► Detail	Quality		
<input checked="" type="checkbox"/>		SI (Service Information)	► Detail	Quality		
<input checked="" type="checkbox"/>		SPPS Site Codes and View	► Detail	Quality		
Supplier Quality Management System (SQMS_SUPPLIER)						

登录后，应显示下图所示界面。


SPPS - Supplier Practical Problem Solving

SPPS Inquiry

	Status	SPPS No	Issue Date	Type	Part Number	Part Description	Supplier DUNS	Supplier Name	Customer DUNS
+	Issued		03-Dec-2018	Quality					
+	Issued			Quality					
+	Issued			Quality					
+	Issued			Quality					
+	CS1-Issued			Quality					
+	Issued			Quality					
+	Issued			Quality					
+	Issued			Supply Chain					

通用汽车记分卡截屏图像

2) 在 SPPS No. 窗口中输入 SPPS 编号。




GM SPPS - Supplier Practical Problem Solving

SPPS Inquiry

Status	SPPS No.	Issue Date	Type	Part Number	Part Description	Supplier DUNS	Supplier Name	Customer DUNS
Issued		03-Dec-2018	Quality					
Issued			Quality					
Issued			Quality					
Issued			Quality					
CS1 - Issued			Quality					
Issued			Quality					
Issued			Quality					
Issued			Supply Chain					

1 - 20 of 11878 items

3) SPPS 系统如下图所示。



GM SPPS - Supplier Practical Problem Solving

Lidia Natanael

SPPS Inquiry

Status	SPPS No.	Issue Date	Type	Part Number	Part Description	Supplier DUNS	Supplier Name	Customer DUNS
Closed		03-Dec-2018	Quality					

4) 单击“导航”按钮，选择“SPPS 记录详细信息”

通用汽车记分卡截屏图像

5) 跳出 SPPS 记录详细信息。单击右上角的按钮，此信息可以 PDF 格式打印。

注：即使通用汽车 SQE 已接受客户的纠正措施计划，已将可采购性级别提高到 3 级或更高级别，认证机构还需要对纠正措施进行验证，并确认对策是否做横向展开。

完整的 SPPS 详细报告示例

下图提供了 SPPS 记录详细信息中的字段和参数的完整列表，并突出显示通用汽车接受的计划。

通用汽车 SQE 的验收以黄色突出显示的字段标识，并标记为“已验证”。

这个实际例子的一些字段已经做了编辑，以删除客户以及涉及的特定产品的信息。

通用汽车记分卡截屏图像

SPPS Record Detail Report generated on 12-Aug-2019 9:42 AM ET

Issue

SPPS Number: 11507

SPPS Type: Quality

SPPS Status: Closed

SPPS Issue Date: 13-Jun-2019 10:18 AM ET

Date Closed: 25-Jul-2019 11:31 AM ET

Supplier: [REDACTED]

Part Number: [REDACTED] RADIATOR ASM-ENG COOL FAN MDL

Problem Description and Method of Validation: PROGRAM: E2UL

ISSUE DESCRIPTION: External threads on Schrader valve, where high pressure sensor mounts, are stripped and the sensor was not fully installed.

PART DISPOSITION: The supplier has 24hrs to request the return of suspect material for analysis and provide a FedEx shipping account number and shipping directions. After that time suspect material may be scrapped by Fairfax.

CONTAINMENT: Immediate containment is required with applicable breakpoints. Please reply to the Containing section of SPPS as required in GM1927-14.

PART IDENTIFICATION: Identify in SPPS response how individual parts will be marked for certification. Identify all certified containers with a green sticker on the parts label with the initials of the person certifying the material, along with the date it was certified. Do NOT cover up any information on the label. GM Fairfax also requires an 8.5x11 inch paper on 2 sides of the container that says 100% certified for (reason for certification), along with the contact name & phone number. If there is more than 1 certification active, then that 1 page needs to list every issue they are certified for. This labeling must continue for 30 days from the start of certification.

CORRECTIVE ACTION DOCUMENTATION: Complete problem solving documentation, PFMEA, process control plan, and documentation/evidence of controls used to avoid repetition for this issue need to be attached in the SPPS system.

TIMING: Failure to meet the required submission deadline may result in a Customer Satisfaction SPPS. If your analysis requires more than 15 working days, you must request an extension. Extension requests must detail why more than 15 days are required and include an expected completion date. E-mail extension requests to the issuer within 15 working days from the date of issuance and note the extension request in the SPPS Planning section data fields.

Person Contacted at Supplier: Not Listed

Manufacture Date(s) of Defect Parts: Unknown

Supplier Parts and/or Process are Out of Spec AND it was not the fault of Customer's applicable process or tooling? YES

Date converted from Supplier Alert (if applicable):

NO

Potential Safety Concern:

Glenn D Griffin [REDACTED]

Customer Issue Owner:

Santosh Sequeira [REDACTED]

Manager Approver for Customer Issue Owner:

Santosh C Sequeira [REDACTED]

19-Jul-2019 5:28 PM ET

Management Confirmation:

ELI ALBERTO SAUCEDO SANCHEZ [REDACTED]

DUNS-Owning SQE

通用汽车记分卡截屏图像

Metrics Data	
Phase:	Production
Customer Quality Impact:	Direct Run Rate
Customer Impact:	Single Occurrence
Furthest Location in the Value Stream the Non-Conformance has Reached:	Part installed in Vehicle/Eng or Trans. Vehicle/Eng or Trans entered as Direct Run/IPPM. As a result Vehicle/Eng or Trans is/was in float.
Last Updated:	Glenn D Griffin, [REDACTED] 13-Jun-2019 10:18 AM ET
Containment at Supplier Location	
Issue Owner at Supplier Location:	Jorge Villanueva, [REDACTED]
Is Containment Required at this location?	YES
Can you meet Daily Requirements?	YES
Describe Containment Actions Taken or Reason for No Containment Action:	Quality Alert was issued and posted in shop floor. Team was informed about the finding. Sensor correctly installed in valve condition has been audited. Parts has been certified identified with material certification sheet. LE237003 192 = OK, 0= NO OK. LD667003 588 = OK, 0= NO OK. LD667003 390 = OK, 0= NO OK. LE237003 468 = OK, 0= NO OK. MD214002 126 = OK, 0= NO OK
Identification of Certified Material:	Sensor correctly installed in valve is marked with blue dot.
Last Updated:	Jorge Villanueva, [REDACTED] 14-Jun-2019 11:24 AM ET
Assessment Status/Reason:	
Assessment Details:	
Supplier Response Details:	

Containment at Issuing Customer Location	
Issuing Customer Location:	007145899 - 18044 - NAO FAIRFAX [REDACTED]
Conforming Material Date (from Containment at Supplier Location):	
Conforming Material ASN (from Containment at Supplier Location):	

通用汽车记分卡截屏图像

Supplier Issue Owner at Customer Location:	Jorge Villanueva, [REDACTED]
Is Containment Required at this location?	NO
Conforming Material Date (from Containment at Customer Location):	24-Jun-2019
ESEP Provider:	
Describe Containment Actions Taken or Reason for No Containment Action:	Problem not noticeable until its in production. Condition can not be surely checked without taking the sensor off.
Identification of Certified Material:	
Last Updated:	Jorge Villanueva, [REDACTED] 14-Jun-2019 11:33 AM ET
Assessment Status/Reason:	
Assessment Details:	
Supplier Response Details:	
Assessment Last Updated:	

Potentially Affected Customer Locations

Customer Location Potentially Affected:

[REDACTED]

Conforming Material Date (from Containment at Supplier Location):

Conforming Material ASN (from Containment at Supplier Location):

Supplier Issue Owner at Customer Location:

Is Containment Required at this location?

Conforming Material Date (from Containment at Customer Location):

ESEP Provider:

Describe Containment Actions Taken or Reason for No Containment Action:

Identification of Certified Material:

Last Updated:

Assessment Status/Reason:

Assessment Details:

Supplier Response Details:

Assessment Last Updated:

Detail Analysis

Root Cause: Sensor was installed incorrectly on condenser valve due to Torque controller was not in fix position (loose condition) and seating fixture did not permit 100% vertical position, providing chances to place sensor in a tilted position.

Last Updated: Jorge Villanueva, [REDACTED] 25-Jun-2019 4:04 PM ET

Assessment Status/Reason:

Assessment Details:

Supplier Response Details:

Assessment Last Updated:

3P Supplier Improvement Activities

Improvement Activity Type:	Predict
BIQS Elements / MMOG-LE Subchapters:	PFMEA
Target Completion Date:	28-Jun-2019
Expected Conforming Material Date:	12-Jul-2019
Actual Completion Date:	12-Jul-2019

通用汽车记分卡截屏图像

First Conforming Material ASN:

Supplier Improvement Activity / Reason for No Supplier Improvement Activity:

Description

Torque/Angle strategy was included as detection control in PFMEA and CP.

Updated By

Jorge Villanueva

Date/Time

12-Jul-2019 12:11 PM ET

Torque/Angle strategy is being included as detection control in PFMEA and CP.

Jorge Villanueva

26-Jun-2019 12:45 PM ET

Supplier Verification Steps Taken:

Description

Torque/Angle strategy was included and evidence is included in presentation.

Updated By

Jorge Villanueva

Date/Time

12-Jul-2019 12:11 PM ET

Approved:

Glenn D Griffin, [REDACTED] 25-Jul-2019 10:12 AM ET

Verified:

ELI ALBERTO SAUCEDO SANCHEZ, [REDACTED] 25-Jul-2019 11:31 AM ET

Assessment Status/Reason:

Verified - Improvement Activity and Verification Steps

Assessment Details:

Supplier Response Details:

Assessment Last Updated:

ELI ALBERTO SAUCEDO SANCHEZ, [REDACTED] 25-Jul-2019 11:31 AM ET

Improvement Activity Type:

Prevent

BIQS Elements / MMSG-LE Subchapters:

Process Change Control

Target Completion Date:

26-Jun-2019

Expected Conforming Material Date:

26-Jun-2019

Actual Completion Date:

26-Jun-2019

First Conforming Material ASN:

Supplier Improvement Activity / Reason for No Supplier Improvement Activity:

Description

Seating fixture was adjust to correct position and allow 100% vertical position, avoiding risk to place sensor in a tilted position. Torque controller arm was installed to fix torque controller device avoiding movement and providing better control for the operator to execute the operation.

Updated By

Jorge Villanueva

Date/Time

12-Jul-2019 12:16 PM ET

Seating fixture was adjust to correct position and allow 100% vertical position, avoiding risk to place sensor in a tilted position. Torque controller arm was installed to fix torque controller device avoiding movement and providing better control for the operator to execute the operation.

Jorge Villanueva

26-Jun-2019 12:44 PM ET

Supplier Verification Steps Taken:

Description

Fixture was adjusted, before and after pictures are included in report presentation. Arm was also installed, evidence is also provided in report presentation.

Updated By

Jorge Villanueva

Date/Time

12-Jul-2019 12:16 PM ET

Approved:

Glenn D Griffin, [REDACTED] 25-Jul-2019 10:12 AM ET

Verified:

ELI ALBERTO SAUCEDO SANCHEZ, [REDACTED] 25-Jul-2019 11:31 AM ET

Assessment Status/Reason:

Verified - Improvement Activity and Verification Steps

Assessment Details:

Supplier Response Details:

Assessment Last Updated:

ELI ALBERTO SAUCEDO SANCHEZ, [REDACTED] 25-Jul-2019 11:31 AM ET

通用汽车记分卡截屏图像

Improvement Activity Type:	Protect
BIQS Elements / MMOG-LE Subchapters:	Standardized Work
Target Completion Date:	26-Jun-2019
Expected Conforming Material Date:	26-Jun-2019
Actual Completion Date:	26-Jun-2019
First Conforming Material ASN:	

通用汽车记分卡截屏图像

Supplier Response Details:			
Assessment Last Updated:	ELI ALBERTO SAUCEDO SANCHEZ [REDACTED] / 25-Jul-2019 11:31 AM ET		
Improvement Activity Type:	Site Read Across		
BIQS Elements:	Process Change Control		
Target Completion Date:	12-Jul-2019		
Actual Completion Date:	12-Jul-2019		
Supplier Improvement Activity / Reason for No Supplier Improvement Activity:	Description Seating fixture was adjusted to correct position and allow 100% vertical position, avoiding risk to place sensor in a tilted position. Torque controller arm was installed to fix torque controller device avoiding movement and providing better control for the operator to execute the operation.	Updated By Jorge Villanueva [REDACTED]	Date/Time 12-Jul-2019 12:29 PM ET
Supplier Verification Steps Taken:	Description Seating fixture was adjusted, before and after evidence was included in report presentation. Torque controller arm also was installed and evidence added to report.	Updated By Jorge Villanueva [REDACTED]	Date/Time 12-Jul-2019 12:29 PM ET
Verified:	ELI ALBERTO SAUCEDO SANCHEZ [REDACTED] / 25-Jul-2019 11:31 AM ET		
Assessment Status/Reason:	Verified - Improvement Activity and Verification Steps		
Assessment Details:			
Supplier Response Details:			
Assessment Last Updated:	ELI ALBERTO SAUCEDO SANCHEZ [REDACTED] / 25-Jul-2019 11:31 AM ET		

通用汽车记分卡截屏图像

Improvement Activity Type:	Site Read Across		
BIQS Elements:	Standardized Work		
Target Completion Date:	14-Jul-2019		
Actual Completion Date:	14-Jun-2019		
Supplier Improvement Activity / Reason for No Supplier Improvement Activity:	<p>Description</p> <p>Operator reinforcement was done on Jun 14 , 2019.</p>	Updated By	Date/Time
		Jorge Villanueva	12-Jul-2019 12:23 PM ET
Supplier Verification Steps Taken:	<p>Description</p> <p>Operator reinforcement was done on Jun 14 , 2019.</p>	Updated By	Date/Time
		Jorge Villanueva	12-Jul-2019 12:23 PM ET
Verified:	ELI ALBERTO SAUCEDO SANCHEZ, [REDACTED]	/ 25-Jul-2019 11:31 AM ET	
Assessment Status/Reason:	Verified - Improvement Activity and Verification Steps		
Assessment Details:			
Supplier Response Details:			
Assessment Last Updated:	ELI ALBERTO SAUCEDO SANCHEZ, [REDACTED]	/ 25-Jul-2019 11:31 AM ET	
Controlled Shipping			
Customer Assessment:			
Created:			
Management Confirmation:			
Assessment Reasoning:			
Exit Criteria:			
Kickoff Meeting Complete Date:			
Date Out:			
Supplier Contact:			
Supplier Owner:			
Controlled Shipping Conforming Material Date:			
Identification of Certified Material at Supplier Location:			
Describe Controlled Shipping Actions Taken:			
Inspection Service Provider:			
Customer Issue Owner Change			
Customer Issue Owner:	Glenn D Griffin, [REDACTED]	/ 13-Jun-2019 10:18 AM ET	

Change Safety Decision

Potential Safety Concern:

Last Updated:

Issue Rescinded

Management Confirmation:

Request to Rescind

Reason for Rescinding Issue:

通用汽车记分卡截屏图像

